

The drawing shows a mechanical assembly with two main components, 1 and 2, connected by a central shaft 7. Component 1 is a complex, curved structure with a central circular opening 8. Component 2 is a rectangular block with a semi-circular cutout. The assembly is shown in two views: a side view (top) and a front view (bottom). The side view shows the profile of the components and the shaft. The front view shows the top and bottom surfaces. Dimensions are indicated by arrows and numbers: 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100. A dimension line with arrows at both ends is labeled 'p'.

1

FIG. 2





fig. 2

FIG. 3




fig. 3